

Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 8/19/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery,



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 8/19/2024

Inspection Photos



Photo 2. Facing northeast toward the tank battery. The oil stained soils at the outlet have not been cleaned up. Tanks labels are missing or peeling off.



Inspection Photos



Photo 3. There is oil stained soils between the tanks from a previous spill. This will need to be reported and cleaned up.



Inspection Photos



Photo 4. There is oil stained soils between the tanks from a previous spill. This will need to be reported and cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 8/19/2024

Inspection Photos



Photo 5. There was a rabbit at the stained soils between the tanks.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 8/19/2024

Inspection Photos



Photo 6. East side of the location facing southwest.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 8/19/2024

Inspection Photos



Photo 7. There are oil stained soils along the flowlines that go to the heater treater.



Inspection Photos



Photo 8. Southeast corner of the location facing northwest toward the tank battery facility.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 476137 | Date: 8/19/2024