

Final Reclamation and Stormwater Inspection

Date: 08/19/2023

Operator: SCHNEIDER ENERGY SERVICES INC - 76840

Location ID: 313900

Inspection Document #: 708201526

Morgan County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 1. Road Base material remains throughout the location, which does not appear to have been contoured and graded to reflect adjacent topography.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 2. Subsidence observed at former location.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 3. Road base material remains throughout the former location.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 4. Facing north near the former well location. Road base material remains throughout.

Inspection Photos
Location Name: Knappe 3
Location ID: 313900



Photo 5. Debris and road base material remains throughout the former location, which does not appear to have been reclaimed per Rule 1004.