

# Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-14 (N8E) Pad

Location #: 333068



Photo # 5703 From entrance to location




Photo # 5704 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-14 (N8E) Pad

Location #: 333068



Aug 21, 2024 at 11:12:45 AM  
CO



Aug 21, 2024 at 11:15:00 AM  
CO

Photo # 5705 Location

Photo # 5706 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY 8-14 (N8E) Pad

Location #: 333068



Photo # 5707 Location