

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-2A1 (B25W) Pad

Location #: 334938



Photo # 5780 From entrance to location




Photo # 5781 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-2A1 (B25W) Pad

Location #: 334938



Photo # 5782 Location



Photo # 5783 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-2A1 (B25W) Pad

Location #: 334938



Photo # 5784 Location



Photo # 5785 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER 25-2A1 (B25W) Pad

Location #: 334938



**Photo # 5786 Flowline heating insulation open ended
/wildlife hazard/available for entry by wildlife**