

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 1 Location.

Photo 2 Frederick A 1 Wellsite.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 3 Frederick A 1 WH.

Photo 4 Frederick C 1 sign is faded, on wrong well and needs to be updated.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 5 Frederick A 1 electric panel & pump jack.



Photo 6 Frederick B 1 wellsite

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 7 Frederick B 1 WH.

Photo 8 Frederick B 1 WH sign.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 9 Frederick B 1 electric panel & pump jack.

Photo 10 Frederick C 1 wellsite.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 11 Frederick C 1 WH.



Photo 12 Frederick D 1 WH sign is faded, on wrong well and needs to be updated.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 13 Frederick C1 electric panel & pump jack.



Photo 14 Frederick D 1 wellsite.

Inspection Photos
Location Name: Frederick Unit A 62N68W-36NENE
Location ID: 336452



Photo 15 Frederick D 1 WH.

Photo 14 Frederick A 1 WH is faded, on wrong well and needs to be updated.