

# Final Reclamation and Stormwater Inspection

Date: 8/14/24

Operator: Klabzuba Oil & Gas Inc - 10148

Location ID: 393646

Inspection Document #: 713900882

Morgan County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: CRONE, B F #1  
Location ID: 393646



**Photo 1.** The photo was taken at the well location facing North. The photo illustrates the meets reclamation standards.



**Photo 2.** The photo was taken at the well location facing East. Refer to the comment for photo 1.



Inspection Photos  
Location Name: CRONE, B F #1  
Location ID: 393646



**Photo 3.** The photo was taken at the well location facing South. Refer to the comment for photo 1.



**Photo 4.** The photo was taken at the well location facing West. Refer to the comment for photo 1.



Inspection Photos  
Location Name: CRONE, B F #1  
Location ID: 393646



**Photo 5.** The reference photo was taken South of the well location facing West. Refer to the comment for photo 1.

The red arrow indicates the area where the tank battery equipment have been removed.