

Interim Reclamation and Stormwater Inspection

Date: 8/14/24

Operator: PCR Operating LLC - 10657

Location ID: 428096

Inspection Document #: 713900895

Morgan County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Hough J Sand Tank Battery

Location ID: 428096



Photo 1. The photo was taken at the tank battery location facing South. The photo illustrates weeds across the tank battery location are unmanaged.

Photo 2. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hough J Sand Tank Battery
Location ID: 428096



Photo 3. The photo was taken at the tank battery location facing West. Refer to the comment for photo 1.



Photo 4. The photo was taken at the tank battery location facing South. Refer to the comment for photo 1.

Inspection Photos
Location Name: Hough J Sand Tank Battery
Location ID: 428096



Photo 5. The photo was taken at the tank battery location facing Southeast. Refer to the comment for photo 1.