

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Aug 21, 2024 at 1:21:19 PM
CO



Aug 21, 2024 at 1:21:23 PM
CO

Photo # 5945 From entrance to location

Photo # 5946 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232




Photo # 5947 Location



Photo # 5948 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5949 Location



Photo # 5950 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5951 Location



Photo # 5952 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5953 Location



Photo # 5954 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5955 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5956 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5957 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5958 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5959 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5960 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5961 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5962 Barbed wire fence needs maintenance/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHIDELER FEDERAL 36-12C (P26W) Pad

Location #: 334232



Photo # 5963 Barbed wire fence needs maintenance/wildlife hazard



Photo # 5964 Barbed wire fence needs maintenance/wildlife hazard