

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/5SENE

Location ID: 334652

Date: 8/20/2024



Southwest Corner of Location – Photo #02978



Wellheads – Photo #02979

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/5SENE

Location ID: 334652

Date: 8/20/2024



Separators – Photo #02983



Tank Battery – Photo #02982

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, KNIGHT-67S95W/5SENE

Location ID: 334652

Date: 8/20/2024



Damaged Fencing – Photo #02981