

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



**Location Overview: Location is within High
Priority/Density/Black Bear/NSO Habitat areas. Location is
approximately 9 yards from West Mamm Creek.
Section/Township/Range: 17 7S92W**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5592 Tunnel erosion & transport of sediment off location



Photo # 5593 Tunnel erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5594 Tunnel erosion & transport of sediment off location



Photo # 5595 Tunnel erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5596 Tunnel erosion & transport of sediment off location



Photo # 5597 Tunnel erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5598 Tunnel erosion & transport of sediment off location



Photo # 5599 Tunnel erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5600 Tunnel erosion & transport of sediment off location

Photo # 5601 Tunnel erosion & transport of sediment off location

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5602 Tunnel erosion & transport of sediment off location



Photo # 5603 Erosion & transport of sediment/insufficient BMP's along spur road to location/sediment migration from slope onto spur road in multiple areas

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC COUEY 17-4 (D17E) Pad
Location #: 324060



Photo # 5604 Erosion & transport of sediment/insufficient BMP's along spur road to location/sediment migration from slope onto spur road in multiple areas



Photo # 5605 Erosion & transport of sediment/insufficient BMP's along spur road to location/sediment migration from slope onto spur road in multiple areas