



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 8/22/2024

Dwinell #4 well. Note: oil stained soil on ground and oil staining at wellhead.

Aug 21, 2024 10:12:57 AM
40.82432124763727N 106.23858681879938W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 8/22/2024

Dwinell #4 excavation
east of well.

Aug 21, 2024 10:13:12 AM
40.82420624792576N 106.238609617576W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 8/22/2024

Dwinell #4 Looking north
with wellhead behind
camera. Note staining on
ground.

Aug 21, 2024 10:13:34 AM
40.82439232617617N 106.23867457732558W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 8/22/2024

Dwinell #4 Excavation
west of wellhead.

Aug 21, 2024 10:13:47 AM
40.824470948427916N 106.23878102749586W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dwinell #4
Location ID: 057-05134
Spill # 487370
Inspection Date: 8/22/2024

Dwinell #4 Excavation
west of wellhead.

Aug 21, 2024 10:13:51 AM
40.824459716677666N 106.23879527673125W
Jc Road 8b
Cowdrey
Jackson County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources