

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Entrance to location - Photo #04539



Location - Photo #04580



**Inspection Photos**  
**Location: TEP ROCKY MOUNTAIN LLC MV/16-9**  
**Location ID: 334717**  
**Date: 8/15/2024**



**Wellheads - Photo #04541**



**Wellheads - Photo #04542**



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Aug 15, 2024 at 12:23:56 PM  
+39.457554,-108.120313 ±4.68m  
De Beque

Separators - Photo #04562



Aug 15, 2024 at 12:31:34 PM  
+39.457761,-108.120407 ±4.69m

Heater Treaters - Photo #04567



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Tank battery - Photo #04577



Location - Photo #04594

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Aug 15, 2024 at 1:00:46 PM  
+39.456649,-108.120180 ±4.71m  
De Beque

SW corner of location - Photo #04595



Location- Photo MV 16-9



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Wildlife hazard - Photo #04547



Wildlife hazard - Photo #04548



**Inspection Photos**  
**Location: TEP ROCKY MOUNTAIN LLC MV/16-9**  
**Location ID: 334717**  
**Date: 8/15/2024**



**Wildlife hazard - Photo #04549**



**Debris - Photo #04551**



**Inspection Photos**  
**Location: TEP ROCKY MOUNTAIN LLC MV/16-9**  
**Location ID: 334717**  
**Date: 8/15/2024**



**Debris - Photo #04552**



**Debris - Photo #04558**



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Aug 15, 2024 at 12:17:48 PM  
+39.456966, -108.119872 ±4.79m

Debris - Photo #04559



Aug 15, 2024 at 12:19:12 PM  
+39.456966, -108.119872 ±4.79m

Debris - Photo #04560



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Debris - Photo #04561



Debris - Photo #04569





## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Debris - Photo #04571



Debris - Photo #04573



## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC MV/16-9

Location ID: 334717

Date: 8/15/2024



Debris - Photo #04574



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources