



Operator: 8 North

Location Name: FABRIZIUS-611N61W 27NWNE

Loc ID: 302924

Inspection: 696301294











CA: Stained Soil at Engine and Exhaust, For localized stained soils or oily waste - Properly dispose of oily waste in accordance with 907.e

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed.

CA: UNUSED EQUIPMENT- Unused Stand, Comply Rule 603.f.

CA Resolution: Unused equipment has been addressed to comply with the 600 series.