

**Operator: 8 North**

**Location Name: FABRIZIUS-611N61W 28NWNW**


**Loc ID: 306452**

**Inspection: 684905209**











**CA:** Debris E of wellhead. Comply with rule 603.f.

**CA Resolution:** Operator has addressed debris on location to comply with the 600 series.

**CA:** Stained soil at wellhead. Comply with Rule 603.f

**CA Resolution:** Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.