

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Entrance to location - Photo #04610



Location - Photo #04637

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Wellheads - Photo #04612



Separators/Dehydrator - Photo #04617

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Tank battery - Photo #04636



NE corner of location - Photo #04646

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



NW corner of location - Photo #04647



SE corner of location - Photo #04650

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Wildlife hazard - Photo #04622



Wildlife hazard - Photo #04623

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Wildlife hazard - Photo #04624



Wildlife hazard - Photo #04630

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Debris - Photo #04634



Debris - Photo #04635

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Debris - Photo #04643



Debris - Photo #04644

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Aug 15, 2024 at 1:58:27 PM
+39.458509, -108.123653 ±4.74m
De Beque



Aug 15, 2024 at 2:03:04 PM
+39.458272, -108.123628 ±4.73m
De Beque

Debris - Photo #04645

Debris - Photo #04651

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL/GM 41-8

Location ID: 334794

Date: 8/15/2024



Debris - Photo #04653



Open ended load line - Photo #04640