

Inspection Photos

API: 055-06201

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location. The location consists mostly of weeds and bare soil.



Inspection Photos



Photo 2. South side of the location facing north. The location consists mostly of weeds and bare soil.



Inspection Photos



Photo 3. North side of the location facing south. The location consists mostly of weeds and bare soil.



Inspection Photos



Photo 4. Halogeten was observed on location which is a noxious weed.



Photo 5. Field bindweed was observed on location which is a noxious weed.



Inspection Photos



Photo 6. Facing northwest toward the surrounding undisturbed pasture.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources