

# Inspection Photos

API: 055-06189

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest toward the access road. Perennial vegetation is progressing along the former road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** West side of the location facing east. There is perennial vegetation establishing but additional seeding should be performed.





## Inspection Photos



**Photo 3.** East side of the location facing west. There are a high amount of sunflowers this season but may not always be present and are not a perennial species. Consider mowing and interseeding.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** East side of the location facing south. There are some areas that could use additional reseeding.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** There is some field bindweed that should be controlled.





## Inspection Photos



**Photo 6.** Facing northwest toward the surrounding undisturbed pasture.

