

# Inspection Photos

API: 055-06195

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** North side of the location facing south. There is perennial vegetation establishing but additional seeding should be performed.





## Inspection Photos



**Photo 2.** South side of the location facing north. There is perennial vegetation establishing but additional seeding should be performed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** There is some field bindweed that should be controlled.





## Inspection Photos



**Photo 4.** Facing east toward the surrounding undisturbed pasture.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources