

# Inspection Photos

API: 055-06196

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing northwest toward the access road and location. There is a landowner road that splits off the right of the photo.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Drone aerial photo facing southwest toward the location. The location was never recontoured and reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Drone aerial photo facing southwest toward the fill slope.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Drone aerial photo facing northwest toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** Drone aerial photo facing southwest toward the cut slope. There are some signs of erosion in this area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 6.** Drone aerial photo facing northeast.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources