

Inspection Photos

API: 055-06186

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing east toward the reclaimed access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:055-06186 | Date: 8/22/2024

Inspection Photos



Photo 2. Drone aerial photo facing east along the access road to the location. This area of the road could use additional seeding.



Inspection Photos



Photo 3. Drone aerial photo facing northeast toward the location. Perennial vegetation appears to be progressing throughout the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Drone aerial photo facing toward the north side of the location. Perennial vegetation appears to be progressing at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Drone aerial photo facing west at the location.

