

Inspection Photos

API: 055-06194

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Drone aerial photo facing south toward the access road and location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Drone aerial photo facing southeast toward the location. It appears the location was previously drill seeded. The vegetation appears to be progressing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Drone aerial photo facing northeast toward the location. It appears the location was previously drill seeded. The vegetation appears to be progressing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources