

# Inspection Photos

API: 055-06212

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 8/22/2024

County: Huerfano



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Drone aerial photo facing west toward the access road. There is a landowner road that splits off the right of the photo.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Drone aerial photo facing west toward the location. The location was never recontoured and reclaimed. Landowner equipment is being stored on the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Drone aerial photo facing west at the location. There are areas with no vegetation and weeds can be seen in areas.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Drone aerial photo facing east toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:055-06212 | Date: 8/22/2024



## Inspection Photos



**Photo 5.** Drone aerial photo facing south toward the undisturbed pasture.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources