

# Final Reclamation Inspection

August 16, 2024

Operator: HIGHPOINT OPERATING CORPORATION - #10071

Location ID: 409326

Inspection Document #: 697505428

Weld County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRC ANDERSON-610N64W 15NENE

Location ID: 409326



**Photo 1.** 2021 aerial imagery illustrates the pit area that had four (4) different pits- see Photo 2. Operator has assumed responsibility for final reclamation of the pit area.



Inspection Photos

Location Name: UPRC ANDERSON-610N64W 15NENE

Location ID: 409326

RECEIVED

DEC 22 99

COGCC

Pawnee Pioneer - Water Disposal Pit  
NeNe Sec. 15- T10N-R64W




Photo 2. Photo illustrates the four (4) different pits.



Inspection Photos

Location Name: UPRC ANDERSON-610N64W

15NENE

Location ID: 409326



**Photo 3.** Photo taken from the eastern access road, facing West. Photo illustrates vegetation establishment along the access road is in-process but additional reclamation activities would be recommended along the eastern half of the access road.



**Photo 4.** Photo taken from the western access road, facing East. See comments under Photo 3. Additional reclamation activities are needed for the western half of the access road.



Inspection Photos

Location Name: UPRC ANDERSON-610N64W

15NENE

Location ID: 409326



**Photo 5.** Photo taken from the northeastern pit area, facing West. Photo illustrates the northern half is mostly vegetated and reflective of reference areas.



**Photo 6.** Photo taken from the northeastern pit area, facing South. See comments under Photo 5.



Inspection Photos

Location Name: UPRC ANDERSON-610N64W

15NENE

Location ID: 409326



**Photo 7.** Photo taken from the central pit area, facing South. Photo illustrates the southern half has a higher abundance of annual, weedy vegetation of tumbleweeds and cheatgrass.



**Photo 8.** Photo taken from the central pit area, facing West. See comments under Photo 7.



Inspection Photos

Location Name: UPRC ANDERSON-610N64W

15NENE

Location ID: 409326



**Photo 9.** Photo taken from the southern pit area, facing South. Photo illustrates a higher abundance of annual, weedy vegetation of tumbleweeds and cheatgrass.



**Photo 10.** Photo taken from the southern pit area, facing East. See comments under Photo 9.