

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

08/13/2024

Document Number:

403852657

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10690 Contact Person: Brent Bongers
Company Name: IMPETRO RESOURCES LLC Phone: (361) 935-5633
Address: 558 CASTLE PINES PKWY UNIT B-4 Fax: ()
City: CASTLE PINES State: CO Zip: 80108 Email: bbongers@impetroresources.com

Identification Information

API Number: 05 - - ECMC Facility ID: 259022 Initial Form 19 or 27 Document number:
Facility Name: LIPPLEMAN P 2 Facility Number: Facility Type: PIT
Location QtrQtr: NENW Section: 31 Township: 3S Range: 51W Meridian: 6
County: WASHINGTON Field Name: CODY
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: CGRS, Inc. Agent Name: Drezden Kinnaird Title: Project Manager
Phone Number: 970-493-7780 Email: dkinnaird@cgrs.com

Rule 909.J Inspection Information

Date the Pit was Inspected 02/29/2024

On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 771069 Facility Name: Lippleman 909J Facility Type: Oil/Gas Production Facility
Location: QtrQtr: NENW Sec: 31 Twp: 3S Range: 51W Meridian: 6
County Name: WASHINGTON Latitude: 39.752826 Longitude: -103.139387

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 120626 Document Name: EDD File Name: 2403008-04RF2 - Impetro 909J 2024 - Lippleman 2 and 4.xlsx
SampleType: Matrix:
Facility ID: 771069 Sample ID: 660252 Sample Name: Lippleman 2 and 4 Sample Date: 02/29/2024
Collection Point: PitDis Matrix: WATER Pre Post: Rule 909.j subsequent sample
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Lab Sample ID: L1711755-01

Batch ID: 121427	Document Name: Rad EDD	File Name: 2403008-04RF2 - Impetro 909J 2024 Rad-Lippleman 2 and 4.xlsx
SampleType:	Matrix:	
Facility ID: 771069	Sample ID: 661133	Sample Name: Lipplemand 2 and 4
Collection Point: PitDis	Matrix: WATER	Pre Post: Rule 909.j subsequent sample
Project Number:	Remediation Number:	Complaint Number: NOAV Number:
Inspection Number:	Spill Number:	Laboratory: Lab Sample ID: L1711756-01

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
771069	403852663	2403008-04RF2 - Impetro 909J 2024 - Lippleman 2 and 4.pdf	Analytical Laboratory Report	PDF
771069	403888342	2403008-04RF2 - Impetro 909J 2024 - Lippleman 2 and 4.pdf	Analytical Laboratory Report	PDF

Sample ECMC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
660252	121-05306	LIPPELMAN 4	Rule 909.j subsequent sample
660252	121-07510	LIPPELMANN 2	Rule 909.j subsequent sample
661133	121-05306	LIPPELMAN 4	Rule 909.j subsequent sample
661133	121-07510	LIPPELMANN 2	Rule 909.j subsequent sample

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. The EDD contained duplicates of chloride and nitrite which were subsequently deleted.	08/23/2024
Total: 1 comment(s)		