

Final Reclamation Inspection

August 16, 2024

Operator: COLORADO ENERGY MINERALS INC - #18615

Facility ID: 119030

Inspection Document #: 697505432

Weld County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: COC-51607
Location ID: 119030

RECEIVED

DEC 22 99

COGCC

Pawnee Pioneer - Water Disposal Pit
NeNe Sec. 15- T10N-R64W




Photo 1. Photo illustrates the four pits utilized for this pit area. The Colorado Energy Minerals pit appears to be the northeastern pit circled in red.

Inspection Photos
Location Name: COC-51607
Location ID: 119030




Photo 2. Photo illustrates the ECMC GIS database for this pit area. This pit appears to be the northeastern pit that was identified in Photo #1.

Inspection Photos
Location Name: COC-51607
Location ID: 119030



Photo 3. Photo taken from the northeastern pit area within the fenced area, facing South. Photo illustrates the pit area meets vegetation Rule 1004 standards.



Photo 4. Photo taken from the northeastern pit area outside the fenced area, facing South. Photo illustrates the pit area meets vegetation Rule 1004 standards.

Note- based on the Photo#1, it would appear that the pit disturbance extended beyond the fenced area.

