

Inspection Photos
Operator: Chemco (OWP)
Location Name: T Wear 1
API: 05-061-06136



Brian Welsh SE Field Inspector COGCC
38.48974, -102.4168, 3909.3ft
08/19/2024 10:20:57

Well is plugged but not cut and capped



Brian Welsh SE Field Inspector COGCC
08/19/2024 10:19:52

Overall location

Inspection Photos
Operator: Chemco (OWP)
Location Name: T Wear 1
API: 05-061-06136



Brian Welsh SE Field Inspector COGCC
38-48962, -102-41697, 3896.6ft
08/19/2024 10:21:37

Looking north from east side of water tank



Brian Welsh SE Field Inspector COGCC
38-48969, -102-41704, 3898.7ft
08/19/2024 10:21:52

Looking west on north side of water tank



Inspection Photos
Operator: Chemco (OWP)
Location Name: T Wear 1
API: 05-061-06136



Looking west from south side of water tank



Looking east on west side of meter shed

Inspection Photos
Operator: Chemco (OWP)
Location Name: T Wear 1
API: 05-061-06136



Looking east on west side of VGS



Looking east on west side of location