

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NWNW

Location ID: 335395

Date: 8/22/2024



Aug 22, 2024 at 12:26:12
11347 US-6
Parachute CO 81635
United States

Location Entrance – Photo #02992



Aug 22, 2024 at 12:28:09
11347 US-6
Parachute CO 81635
United States

Wellheads – Photo #02996

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NWNW

Location ID: 335395

Date: 8/22/2024



Separators – Photo #02994



Tank Battery – Photo #02993

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-66S95W/34NWNW

Location ID: 335395

Date: 8/22/2024



Insufficient Erosion Control – Photo #02995