

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

12/02/2023

Document Number:

403612800

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10797 Contact Person: Wesley Marshall
Company Name: DESERT EAGLE OPERATING LLC Phone: (214) 886-5098
Address: 17101 PRESTON RD SUITE 105 Fax: ()
City: DALLAS State: TX Zip: 75248 Email: wmarshall@prohelium.com

Identification Information

API Number: 05 - - ECMC Facility ID: 484357 Initial Form 19 or 27 Document number:
Facility Name: Red Rocks Facility Number: 1-14 Facility Type: LOCATION
Location QtrQtr: NENW Section: 1 Township: 30S Range: 55W Meridian: 6
County: LAS ANIMAS Field Name:
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Dynamic Energy Consulting Agent Name: CATHY BULF Title: Manager
Phone Number: 719-440-9906 Email: cathybulf@gmail.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 484674 Facility Name: Red Rocks 1-14 Facility Type: Helium Gas Well
Location: QtrQtr: NENW Sec: 1 Twp: 30S Range: 55W Meridian: 6
County Name: LAS ANIMAS Latitude: 37.465273 Longitude: -103.526247

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 114907 Document Name: Red Rocks 1-14 Baseline File Name: RR 1-14 Baseline.xlsx
Sample Type: Matrix:
Facility ID: 484674 Sample ID: 654044 Sample Name: Red Rocks 1-14 Baseline Sample Date: 10/02/2023
Collection Point: Soil Matrix: SOIL Pre Post: 806.a-UIC initial Analysis
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: Eurofins Eaton Analytical Inc. Lab Sample ID: 280-182262-4

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	08/26/2024
Total: 1 comment(s)		