




<b>SITE NAME:</b> Open 10-25							<b>DATE:</b> 5/23/2024	<b>REM. PROJECT #:</b>	<b>WEATHER:</b> Sunny, 60 F		
<b>SITE DIRECTIONS:</b> Cr 47 & Cr 16, E 0.2, N into							<b>CLIENT:</b> OXY				
<b>LEGALS AND LAT/LONG:</b> 40.107550,-104.609960							<b>TASMAN PERSONNEL:</b> PD				
<b>SOIL TYPES:</b> Silty Sand - SM							<b>SURFACE GRADIENT:</b> East				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
5/23/2024 08:30	WH-B01@6'	3.5	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
5/23/2024 08:32	WH-N01@5'	2.6	No Staining	No Odor	Yes	N/A	Separator				
5/23/2024 08:34	WH-S01@5'	4.0	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
5/23/2024 08:36	WH-E01@5'	3.7	No Staining	No Odor	Yes	N/A	Dump Line				
5/23/2024 08:38	WH-W01@5'	2.8	No Staining	No Odor	Yes	N/A	Wellhead				
5/23/2024 08:40	WHS-N01@3"	0.8	No Staining	No Odor	Yes	N/A	Flowline				
5/23/2024 08:42	WHS-S01@3"	0.7	No Staining	No Odor	Yes	N/A	Other:				
5/23/2024 08:44	WHS-E01@3"	1.8	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
5/23/2024 08:46	WHS-W01@3"	2.1	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
5/23/2024 08:48	BG-01@3'	2.2	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
5/23/2024 08:50	BG-01@6'	1.8	No Staining	No Odor	Yes	Lab	Date	Number	CY		
5/23/2024 08:52	BG-02@3'	1.8	No Staining	No Odor	Yes	Lab					
5/23/2024 08:54	BG-02@6'	1.7	No Staining	No Odor	Yes	Lab					
5/23/2024 08:56	BG-03@3'	1.9	No Staining	No Odor	Yes	Lab					
5/23/2024 08:58	BG-03@6'	2.1	No Staining	No Odor	Yes	Lab					
5/23/2024 09:00	FL-B01@4'	2.0	No Staining	No Odor	Yes	Lab	Total Removed		0	0	
5/28/2024 12:58	FL-B02@4'	1.2	No Staining	No Odor	Yes	N/A	Disposal Facility:				
5/28/2024 13:00	FL-B03@4'	2.1	No Staining	No Odor	Yes	Lab	Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				



<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b> Water observed in photo is due P&A Activities - groundwater not encountered			

<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>			



<b>Equipment ID:</b>		<b>Equipment Type:</b>		<b>Equipment ID:</b>		<b>Equipment Type:</b>	
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>		<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	
<b>Notes/Conditions:</b>				<b>Notes/Conditions:</b>			

					
<b>Equipment ID:</b>		<b>Equipment Type:</b>	<b>Equipment ID:</b>		<b>Equipment Type:</b>
<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>	<b>Material:</b>	<b>Volume:</b>	<b>Contents:</b>
<b>Notes/Conditions:</b>			<b>Notes/Conditions:</b>		