


Operator: 8 North

Location Name: FABRIZIUS-611N61W 28NWNW

Loc ID: 302854

Inspection: 696301302





CA: Stained Soil at Wellhead: For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 907.e."" Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

CA Resolution: Operator has provided photo evidence showing that the stained soil at the wellhead has been addressed in compliance with the 900 and 600 series.