

**Storm Water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Location Overview: Location is within High Priority/Density  
Habitat areas & in close proximity to Bald Eagle Roost site.  
Location is approximately 24 yards from a creek/drainage that  
contributes to the Colorado River.  
Section/Township/Range: 13 6S94W**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6259 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**



**Photo # 6260 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6261 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**

**Photo # 6262 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6263 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**

**Photo # 6264 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location (S/SW edge of pad near wellhead)**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6265 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location**

**Photo # 6266 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6267 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location**



**Photo # 6268 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location**

**Storm water Management and Erosion control**  
**Location Name: TEP Rocky Mountain LLC CLOUGH RWF 14-13 Pad**  
**Location # 324285**



**Photo # 6269 Erosion & transport of sediment off location & into vegetated areas/failure to minimize erosion & the transport of sediment off location**