

# Inspection Photos

August 21st, 2024

Operator: Seeley Oil Company - 10506

Location ID: 322116

Inspection Document #: 714001115

Dolores County, CO

Township: SESW 7 38N 19W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Island Butte 3  
Location ID: 322116

8/21/24  
+37.840015,-109.462315  
319° NW



**Photo 1.** View of disturbance taken from the access point facing center.



API #: 083-06115





Inspection Photos  
Location Name: Island Butte 3  
Location ID: 322116



8/21/24  
+37.839823,-109.462323  
282° W

**Photo 2.** Guy line anchors are properly marked.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 083-06115



Inspection Photos  
Location Name: Island Butte 3  
Location ID: 322116



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Weedy Russian thistle debris observed in a large patch in the center of the disturbance.

API #: 083-06115



Inspection Photos  
Location Name: Island Butte 3  
Location ID: 322116



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** View of the western interim reclamation area facing southwest.

API #: 083-06115



Inspection Photos  
Location Name: Island Butte 3  
Location ID: 322116



**Photo 5.** Reference area comprised of Juniper, Sagebrush and Crested wheatgrass.

