

# Inspection Photos

August 21st, 2024

Operator: Kinder Morgan - 46685

Location ID: 322104

Inspection Document #: 714001121

Dolores County, CO

Township: NENE 19 40N 17W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: DWD 1  
Location ID: 322104



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 1.** View of disturbance taken from the access point facing center. Note: Variance approved to waive reclamation of flat section of pad with COA's for cut slopes, see photo 2.

API #: 033-06078

Inspection Photos  
Location Name: DWD 1  
Location ID: 322104



**Photo 2.** Per variance doc #402036452 location cut slopes have been revegetated to ECMC's 80% standards and recontoured to a slope aspect of 3:1.

Inspection Photos  
Location Name: DWD 1  
Location ID: 322104



8/21/24  
+37.719913,-108.758386  
295° NW

**Photo 3.** Musk thistle has been removed from the western portion of the disturbance.

Inspection Photos  
Location Name: DWD 1  
Location ID: 322104

8/21/24  
+37.719531,-108.758321  
242° SW



**Photo 4.** Reference area comprised of Juniper, Rabbitbrush and Serviceberry.