

Final Reclamation and Stormwater Inspection

Date: 08/20/2024

Operator: PDC ENERGY INC - 69175

Location ID: 333296

Inspection Document #: 708201535

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 1. Red polygon illustrates approximate location of former PDC wells. It does not appear that the former well location has been reclaimed with evidence of road base material still observed. This portion of the former location does not appear to be in use by the active tank battery operated by Extraction Oil & Gas.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 2. Facing south; see comments in Photo 2.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photos 3 & 4. Facing southeast and southwest at the former tank battery. The tank battery does not appear to be progressing towards Rule 1004 standards with evidence of undesirable vegetation (kochia and russian thistle) observed throughout.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 5. Google Earth aerial imagery (circa 04/2010) illustrating the Great Western/PDC location footprint prior to any additional oil and gas activity. Red outlines indicated wells, tank battery, and approximate extent of original disturbance.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 6. Google Earth aerial imagery (circa 08/2012) illustrating the Great Western/PDC location after interim reclamation activities were performed.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 7. Google Earth aerial imagery (circa 07/2019) illustrating the Great Western/PDC location after the active tank battery operated by Extraction Oil & Gas was constructed and before the Great Western/PDC location underwent final reclamation.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 8. Google Earth aerial imagery (circa 05/2023) illustrating the Great Western/PDC location after the wells and tank battery were decommissioned.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296



Photo 9. Green polygon illustrates areas that require additional final reclamation activities. Note - green polygon is only approximate as this area does not appear to be in use by the active tank battery location.

Inspection Photos
Location Name: Great Western 66N67W
Location ID: 333296




Photo 10. Construction layout drawings from active tank battery location operated by Extraction Oil & Gas (doc #400380371). Photo illustrates the disturbance area for the Extraction Oil & Gas tank battery with the preexisting Great Western/PDC location to the west of the outlined disturbance area.