

# Inspection Photos

Loc: 321883

Operator: WIEPKING-FULLERTON ENERGY LLC

Inspection Date: 8/19/2024

County: CHEYENNE



## Inspection Photos



**Photo 1.** Facing east toward the reclaimed access road.



## Inspection Photos



**Photo 2.** Facing southwest toward the location. The perennial vegetation is progressing well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321883 | Date: 8/19/2024

## Inspection Photos



**Photo 3.** Facing east toward the location. The perennial vegetation is progressing well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:321883 | Date: 8/19/2024

## Inspection Photos



**Photo 4.** Facing northeast toward the location. The perennial vegetation is progressing well.

