

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

## ECMC RECEPTION

Receive Date:

08/12/2024

Document Number:

403885741

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:  
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION  
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6  
County: WELD Field Name:  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772200 Facility Name: Child 235335 Facility Type: Domestic Well  
Location: QtrQtr: NWNE Sec: 26 Twp: 1N Range: 68W Meridian: 6  
County Name: BROOMFIELD Latitude: 40.029003 Longitude: -104.969925

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 121354 Document Name: Size of file in bytes: 12902 File Name: 2024\_05\_20\_Child 235335 Isotech NG4 ECMC.xlsx  
SampleType: Matrix:  
Facility ID: 772200 Sample ID: 661061 Sample Name: Child 235335 Sample Date: 05/20/2024  
Collection Point: Dom Matrix: GAS Pre Post: Voluntary Post drill  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 923600

Batch ID: 121351		Document Name: Size of file in bytes: 28150		File Name: 2024_05_20_Child 235335 SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772200	Sample ID: 661058	Sample Name: Child 235335		Sample Date: 05/20/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA64476-1		

  

Batch ID: 121354		Document Name: Size of file in bytes: 12902		File Name: 2024_05_20_Child 235335 Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772200	Sample ID: 661062	Sample Name: Child 235335		Sample Date: 05/20/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 923600		

  

Batch ID: 121353		Document Name: Size of file in bytes: 11271		File Name: 2024_05_20_Child 235335 Isotech SIW ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772200	Sample ID: 661060	Sample Name: Child 235335		Sample Date: 05/20/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 923547		

  

Batch ID: 121352		Document Name: Size of file in bytes: 11584		File Name: 2024_05_20_Child 235335 Trip Blank SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 772200	Sample ID: 661059	Sample Name: Child 235335		Sample Date: 05/20/2024	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA64479-1		

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
772200	403885774	2024_05_20_Child_235335_FS_ECMC.pdf	Field Data Report	PDF
772200	403885776	2024_05_20_Child_235335_Loc.jpg	Photographs	JPG
772200	403885772	2024_05_20_Child 235335 SGS.pdf	Analytical Laboratory Report	PDF
772200	403885783	2024_05_20_Child_235335_Wellhead.jpg	Photographs	JPG
772200	403885758	2024_05_20_Child 235335 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772200	403885778	2024_05_20_Child_235335_PrePostPurge.jpg	Photographs	JPG
772200	403885752	2024_05_20_Child 235335 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772200	403885766	2024_05_20_Child 235335 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772200	403885780	2024_05_20_Child_235335_Spigot.jpg	Photographs	JPG

**Sample ECMC Well Related:**

No Sample ECMC Well Related Information Provided.

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	The data submitted by the operator can be accessed through COGIS data system.	08/28/2024
Total: 1 comment(s)		