

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325914

Inspection Document #: 71400112

La Plata County, CO

Township: SENW 23 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Tycksen A 1
Location ID: 325914




Photo 1. View of well disturbance taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07161

Inspection Photos
Location Name: Tycksen A 1
Location ID: 325914



Photo 2. Impacted surface material has been removed from around the well head.

Inspection Photos

Location Name: Tycksen A 1

Location ID: 325914



Inspection Photos

Location Name: Tycksen A 1

Location ID: 325914



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area comprised of Pine, Smooth brome and Western wheatgrass.

API #: 067-07161