

Inspection Photos

August 23rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 326650

Inspection Document #: 714001135

La Plata County, CO

Township: SWNE 20 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cundiff C2
Location ID: 326650



Photo 1. View of well pad taken from the access point facing center.



Inspection Photos
Location Name: Cundiff C2
Location ID: 326650



Photo 2. View of the northern interim reclamation area facing Northwest.

Inspection Photos
Location Name: Cundiff C2
Location ID: 326650



Photo 3. View of rutting/erosional channels along the access road. Additional stabilization, storm water BMP maintenance is needed to minimize degradation to access road.

Inspection Photos
Location Name: Cundiff C2
Location ID: 326650



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area comprised of Squirrel tail, Pine and Gambel oak.

API #: 067-08629