

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Photo 1 – Well Sign

Photo 2 – Pumping Unit

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Photo 3 – Wellhead



Photo 4 – Water Tank

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Photo 5 – Labels fading – Replace soon



Photo 6 – Berms Inadequate

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Photo 7 – Water Tank – Berms Inadequate



Photo 8 – Water Tank – Berms Inadequate

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Energy and Carbon Management Commission
40.61195, -103.7152, 4581.4ft
08/20/2024 14:02:22

Photo 9 – Heater Treater



Energy and Carbon Management Commission
40.61182, -103.71522, 4576.4ft
08/20/2024 14:02:33

Photo 10 – Tank Battery

Inspection Photos
Location Name: Bounty #1
Location ID: 329914



Photo 11 – Tank Battery Sign



Photo 12 – Tank Battery – Backside of Tanks