

**Operator: 8 North**

**Location Name: FABRIZIUS-611N61W 33SESE**

**Loc ID: 302847**

**Inspection: 696301274**



**CA:** UNUSED EQUIPMENT- Unused Chemical Tank and Containment. Comply with Rule 603.f.

**CA Resolution:** Unused equipment has been removed to comply with the 600 series.