

Operator: 8 North

Location Name: RAY STATE-611N61W 16SWSW

Loc ID: 305676

Inspection: 684905105





CA: Stained soil at engine, exhaust. Corrective Action: Comply with rule 603.f

CA Resolution: Operator has provided photo evidence to show that the stained soil has been appropriately removed/cleared and mechanical issues leading to the leak have also been addressed to comply with the 600 and 900 series.