

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC Federal 7007E-2 (H2SW) Pad**  
**Location ID: 324340**



**Location Overview: Location is within Black Bear Habitat area  
& in close proximity to High Priority/NSO Habitat areas.  
Location is approximately 400 yards from Middle Mamm  
Creek.**

**Section/Township/Range:**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC Federal 7007E-2 (H2SW) Pad**  
**Location ID: 324340**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC Federal 7007E-2 (H2SW) Pad**  
**Location ID: 324340**



**Photo # 7116 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill.**



**Photo # 7117 Failure to maintain chemical BMP - Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill. (Standing fluid on chemical containment is also a wildlife hazard)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC Federal 7007E-2 (H2SW) Pad**  
**Location ID: 324340**



**Photo # 7118 Erosion & transport of sediment off location/failure to minimize erosion & transport of sediment (near pig station at entrance to location)**



**Photo # 7119 Erosion & transport of sediment off location/failure to minimize erosion & transport of sediment (near pig station at entrance to location)**



**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC Federal 7007E-2 (H2SW) Pad**  
**Location ID: 324340**



**Photo # 7120 Erosion & transport of sediment off  
location/failure to minimize erosion & transport of sediment  
(near pig station at entrance to location)**