

Surface Cement Verification Report

Cementer's Well Service, Inc.
 P.O. BOX 336220 • GREELEY, CO 80633 •
 (970) 690-1100

Speed Goat Fed 3432 - 06H

Date: Apr 15, 2024

CLIENT: Verdad Resources, LLC

FIELD TICKET #: 300.0147.009



COGCC Operator Guidance - RULE #308.A.B(2)A.ii

Job Information

| | | | |
|--------------------------|------------------------|----------------------------|-------------------------------|
| API #: | 05-123-52503 | Job Type: | New Well -- Surface |
| Well Owner: | Verdad Resources, LLC | Cementing Company: | Cementer's Well Service, Inc. |
| Lease: | Speed Goat Fed | Contact: | Nate Kvamme, 303-324-4296 |
| Well Name: | 3432 - 06H | Ambient Conditions: | |
| State: | CO | Temperature: | deg F |
| County: | Weld | | |
| Job Date: | Apr 15, 2024 | | |
| Time on Location: | Apr 14, 2024, 11:00 PM | | |

Slurry Description

| | |
|----------------------------------|---|
| a) Purpose | Surface |
| b) Cement Class | Portland Type I/II |
| c) Cement Yield | 1.61 cu ft / sk |
| d) Cement Density | 13.9 PPG |
| e) Number of sks | 699 sks |
| f) Mix Fluid Type | |
| Water / Cement | 8.5 gal/sk |
| g) Slurry Mixed | 200.43 BBLs Cement |
| h) Additives Used | Gel/Bentonite 3.00 % Calcium Chloride 1.50 % |
| Total Water Used | 278.57 BBLs Water |
| i) Displacement Fluid Vol | 117.11 BBLs Water |
| j) Method of Placement | N/A |
| l) Stage Tool Depth | N/A |
| k) Set Depth | Pipe Landed @ 1,559 ft. |
| m) Float Collar Depth | Plug Landed @ 1,515 ft. |
| n) Designed top of Cement | Returns to Surface (+) |
| o) Centralizer Depths | N/A |

Job Notes

| | |
|--|-----------------------|
| a) Plug Down | |
| Yes @ Apr 15, 2024, 2:00 AM | |
| Landed Plug @ | 1,595 PSI |
| Final Lift @ | 475 PSI |
| b) Floats Held | Yes 1.0 BBLs back |
| c) Full Returns | Yes |
| Lost Circulation | No |
| d) Cement to Surface | Yes |
| | 30 BBLs Cement |
| e) If no returns, top off | |
| f) Top off Detail | |
| g) Additional Detail | |
| Charts - | |
| (Pressure, Density, Pump Rate & Total BBLs) | |
| | *see further attached |

Cementer's Well Service, Inc.

Verdad Resources, LLC

Cementer's Job ID: 3753

Surface Cement Verification Report

Cementer's Well Service, Inc.
 P.O. BOX 336220 • GREELEY, CO 80633 •
 (970) 690-1100

Speed Goat Fed 3432 - 06H

Date: Apr 15, 2024

CLIENT: Verdad Resources, LLC

FIELD TICKET #: 300.0147.009



COGCC Operator Guidance - RULE #308.A.B(2)A.ii

Job Information

| | | | |
|--------------------------|------------------------|----------------------------|-------------------------------|
| API #: | 05-123-52503 | Job Type: | New Well -- Surface |
| Well Owner: | Verdad Resources, LLC | Cementing Company: | Cementer's Well Service, Inc. |
| Lease: | Speed Goat Fed | Contact: | Nate Kvamme, 303-324-4296 |
| Well Name: | 3432 - 06H | Ambient Conditions: | |
| State: | CO | Temperature: | deg F |
| County: | Weld | | |
| Job Date: | Apr 15, 2024 | | |
| Time on Location: | Apr 14, 2024, 11:00 PM | | |

Slurry Description

| | |
|----------------------------------|---|
| a) Purpose | Surface |
| b) Cement Class | Portland Type I/II |
| c) Cement Yield | 1.61 cu ft / sk |
| d) Cement Density | 13.9 PPG |
| e) Number of sks | 699 sks |
| f) Mix Fluid Type | |
| Water / Cement | 8.5 gal/sk |
| g) Slurry Mixed | 200.43 BBLs Cement |
| h) Additives Used | Gel/Bentonite 3.00 % Calcium Chloride 1.50 % |
| Total Water Used | 278.57 BBLs Water |
| i) Displacement Fluid Vol | 117.11 BBLs Water |
| j) Method of Placement | N/A |
| l) Stage Tool Depth | N/A |
| k) Set Depth | Pipe Landed @ 1,559 ft. |
| m) Float Collar Depth | Plug Landed @ 1,515 ft. |
| n) Designed top of Cement | Returns to Surface (+) |
| o) Centralizer Depths | N/A |

Job Notes

| | |
|--|-----------------------|
| a) Plug Down | |
| Yes @ Apr 15, 2024, 2:00 AM | |
| Landed Plug @ | 1,595 PSI |
| Final Lift @ | 475 PSI |
| b) Floats Held | Yes 1.0 BBLs back |
| c) Full Returns | Yes |
| Lost Circulation | No |
| d) Cement to Surface | Yes |
| | 30 BBLs Cement |
| e) If no returns, top off | |
| f) Top off Detail | |
| g) Additional Detail | |
| Charts - | |
| (Pressure, Density, Pump Rate & Total BBLs) | |
| | *see further attached |

Cementer's Well Service, Inc.

Verdad Resources, LLC

Cementer's Job ID: 3753