

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403899973

Date Received:

08/26/2024

Spill report taken by:

CANFIELD, CHRIS

Spill/Release Point ID:

486743

### SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: <u>CRESTONE PEAK RESOURCES OPERATING LLC</u>	Operator No: <u>10633</u>	<b>Phone Numbers</b>
Address: <u>555 17TH STREET SUITE 3700</u>		Phone: <u>(720) 3846452</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>( )</u>
Contact Person: <u>Costin McQueen</u>		Email: <u>cmcqueen@civiresources.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403787719

Initial Report Date: 05/13/2024 Date of Discovery: 05/10/2024 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR SWNW SEC 26 TWP 4S RNG 65W MERIDIAN 6

Latitude: 39.675830 Longitude: -104.638887

Municipality (if within municipal boundaries): Aurora County: ARAPAHOE

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

#### Reference Location:

Facility Type: TANK BATTERY  Facility/Location ID No 455198

Spill/Release Point Name: Chico 4-65 26-25  Well API No. (Only if the reference facility is well) 05- -

No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): >=5 and <100

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Cloudy/Overcast

Surface Owner: FEE

Other(Specify): \_\_\_\_\_

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

A compromised valve resulted in approximately 10 bbls of fluid to spill to the pad surface. The spill was contained entirely on pad and a vac truck was immediately dispatched to begin cleanup activities. The impacted soil will be removed and hauled for disposal. Confirmation soil samples will be collected and submitted in compliance with ECOM Table 915-1. A waste characterization sample was collected during the initial spill assessment. Analytical results will be provided on a supplemental form.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
5/10/2024	CPW	Lexi Hamous-Miller	-on file	Notified of Release
5/10/2024	Surface Owner	on file	-on file	Notified of Release
5/10/2024	City of Aurora LGD	Jeffrey Moore	-on file	Notified of Release
5/10/2024	ECMC EPS	Chris Canfield	-on file	Notified of Release

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

Yes Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: n/a Public Water System: n/a

Residence or Occupied Structure: n/a Livestock: n/a

Wildlife: Threatened to Impact Publicly-Maintained Road: n/a

Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

Yes Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)

Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_

Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_

Was there damage during excavation? \_\_\_\_\_

Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

No Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location     Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

### SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 05/10/2024

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	<u>5</u>	<u>0</u>	<input type="checkbox"/>
CONDENSATE	<u>0</u>	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	<u>5</u>	<u>0</u>	<input type="checkbox"/>
DRILLING FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	<u>0</u>	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	<u>0</u>	<u>0</u>	<input type="checkbox"/>

specify: \_\_\_\_\_

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

**A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit**

Impacted Media (Check all that apply)     Soil     Groundwater     Surface Water     Dry Drainage Feature

Surface Area Impacted: \_\_\_\_\_ Length of Impact (feet): \_\_\_\_\_ Width of Impact (feet): \_\_\_\_\_

Depth of Impact (feet BGS): \_\_\_\_\_ Depth of Impact (inches BGS): \_\_\_\_\_

How was extent determined?

The extent was determined through visual delineation and will be confirmed through confirmation soil sampling.

Soil/Geology Description:

SC - clayey sand

Depth to Groundwater (feet BGS) 200                      Number Water Wells within 1/2 mile radius: 1

If less than 1 mile, distance in feet to nearest

Water Well	<u>1195</u>	None	<input type="checkbox"/>	Surface Water	<u>1605</u>	None	<input type="checkbox"/>
Wetlands	_____	None	<input checked="" type="checkbox"/>	Springs	_____	None	<input checked="" type="checkbox"/>
Livestock	<u>514</u>	None	<input type="checkbox"/>	Occupied Building	<u>2524</u>	None	<input type="checkbox"/>

Additional Spill Details Not Provided Above:

The closest water well (DWR Permit # 311804) had a reported static water level of 200' bgs. Based on depth to groundwater and the surficial nature of the release, Crestone requests the use of RSSL concentrations to show compliance with ECMC Table 915-1.

## CORRECTIVE ACTIONS

#1 Supplemental Report Date: 08/26/2024

Root Cause of Spill/Release Corrosion

Other (specify)

Type of Equipment at Point of Spill/Release: Process Piping

If "Other" selected above, specify or describe here:

Describe Incident & Root Cause (include specific equipment and point of failure)

A compromised valve resulted in approximately 10 bbls of fluid to spill to the pad surface. The spill was contained entirely on pad and a vac truck was immediately dispatched to begin cleanup activities.

Describe measures taken to prevent the problem(s) from reoccurring:

In addition to routine AVO inspections, Crestone implemented an upgraded integrity management program focusing on the reduction of internal corrosion related releases. This program includes increased pressure testing and preventative maintenance frequencies, installation of anodes and fluid detection kill switches on tanks and production vessels, and updating facility designs to utilize more corrosion resistant materials.

Volume of Soil Excavated (cubic yards): 4

Disposition of Excavated Soil (attach documentation)  Offsite Disposal  Onsite Treatment

Other (specify)

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:  Corrective Actions Completed (documentation attached, check all that apply)

Horizontal and Vertical extents of impacts have been delineated.

Documentation of compliance with Table 915-1 is attached.

All E&P Waste has been properly treated or disposed.

Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: 36702

SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

## OPERATOR COMMENTS:

A Form 27 to continue the remedial work on this spill was submitted on 7/23/2024. The cleanup of this spill will continue under REM # 36702

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Costin McQueen

Title: Senior Env Specialist Date: 08/26/2024 Email: cmcqueen@civiresources.com

**COA Type****Description**

	Quarterly reporting (90 days) is required under Remediation Project #36702. Operator shall include the Spill ID associated with this form on the subsequent Supplemental Form 27 and select Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912 in addition to the previous Rule selection.
1 COA	

**ATTACHMENT LIST****Att Doc Num****Name**

403899973	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403905150	FORM 19 SUBMITTED

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)