

## Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685

Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/28/2024 Inspection Doc#: 693807677



Location overview looking N



Injection wellhead housing  
Secondary containment of chemicals

## Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685

Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/28/2024 Inspection Doc#: 693807677



Tank Battery



Manifold Housing and control station

# Inspection Photos

Operator: KINDER MORGAN CO2 CO LLC – 46685


Location Name: MCELMO DOME UNIT 26-38-18 #YWD-1

Location ID: 313469 API #: 05-083-06195

Inspection Date: 8/28/2024 Inspection Doc#: 693807677



Offload station



Sensor readout panel