

# Inspection Photos

API: 017-06654

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/28/2024

County: Cheyenne



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south at the location. The access road intersects the abandoned location. There are impacted areas on both sides of the road.





## Inspection Photos



**Photo 2.** Facing southeast on the east side of the road at the abandoned location. This area has impacted crop growth. This area is approximately 160' x 60' with no crop growth.





## Inspection Photos



**Photo 3.** Facing southwest at the location. The area on the west side of the road also has impacted crop growth..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Facing northeast toward the undisturbed crop field which has a uniform crop cover.

