

Inspection Photos

ID: 480416

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/28/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the Arapahoe Unit Tank Battery. Some of the tanks have missing or faded labeling.



Inspection Photos



Photo 2. There are some oil stained soils at the pipe outlet that need to be cleaned up.



Inspection Photos



Photo 3. Facing northeast at the tank battery. There are stained soils from a spill that occurred at the backside of the tanks. The spill was contained in the secondary containment..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480416 | Date: 8/28/2024

Inspection Photos



Photo 4. Facing north at the spill that appears to have occurred at the tank battery.



Inspection Photos



Photo 5. Facing northwest at the spill that appears to have occurred at the tank battery.



Inspection Photos



Photo 6. Facing northeast at the location. There is unused equipment near the separator that must be removed.



Inspection Photos



Photo 7. Facing toward the southeast side of the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID: 480416 | Date: 8/28/2024

Inspection Photos



Photo 8. This chemical containment has oily sludge and no wildlife protections. The labels are faded and need to be updated.

