

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #1 sign on location

SHAWNEE OIL
DILL GULCH 1-17
NE/4-SW/4 SEC. 17 5NR89W
LEASE 103840

Aug 28, 2024 9:45:42 AM
40.38549747783691N 107.40415549837053W
400 West Lincoln Avenue
Hayden
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 107-06019
Inspection Date: 8/28/2024

Photo #2 hammer union
behind location sign.

Aug 28, 2024 9:45:55 AM
40.385512481443584N 107.40414753556252W
400 West Lincoln Avenue
Hayden
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #3 3-210BBL AGT in dirt berm. Photo is taken looking north-northwest. Tank on the left of photo is referred to as the “south tank” in this document.



Aug 28, 2024 9:50:13 AM
40.385427488945425N 107.40426890552044W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #4 tank on right is the South tank tank (of 3-210BBL tanks) The water in the photo center was coming out of the tank from a hole in the tank. The hole was approximately 6" from the bottom of the tank.

Aug 28, 2024 9:47:04 AM
40.385560425929725N 107.40435398183763W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #5 water leaking from the side of the tank. The flow was estimated at less than 1 Gallon per minute.

Aug 28, 2024 9:46:51 AM
40.38552911952138N 107.40435808897018W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Dill Gulch 1-17
Location ID: 107-06019
Inspection Date: 8/28/2024

Photo #6 water leaking
from the side of the tank.
The flow was estimated
at less than 1 Gallon per
minute.

Aug 28, 2024 9:46:49 AM
40.385529077611864N 107.40435808897018W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #7 leak as viewed
from the other side of the
tank.



Aug 28, 2024 9:46:28 AM
40.38552149198949N 107.40431483834982W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:47:17 AM
40.38555636070669N 107.40435817278922W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #8 water pooled in the secondary containment. Historic aerial show that water has been pooled in the tank battery for many years. COGCC inspection history has noted water in secondary containment in 2012. Note: black staining at far side of photo, the staining was oil.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:47:15 AM
40.385559001006186N 107.40435674786568W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #9 secondary containment. Photo looking north. Note: water and oil were observed in water and soil.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:50:47 AM
40.38556985557079N 107.40426823496819W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #10 looking west between the north tank (on right) and middle tank to left of photo. The white tank, does not appear to be in service. The tank is from a water truck.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:50:37 AM
40.385541818104684N 107.40427209064364W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #11 Tank at left of photo is the South tank.
Note: oil staining at the base of the middle tank.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #12 south side of the tank battery. Access road on left of photo.



Aug 28, 2024 9:50:16 AM
40.38543331436813N 107.40425775758922W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #13 North end of
the secondary
containment. Oil on water
and in tank battery.

Aug 28, 2024 9:50:59 AM
40.385607071220875N 107.40423747338355W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:56:40 AM
40.385432979092N 107.40421626716852W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #14 Catwalk
between the north and
middle tank. Note: the
walk board appears to be
dipping down where the
staircase attaches.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #15 piping
between the south tank
and middle tank.

Aug 28, 2024 9:56:36 AM
40.38543473929167N 107.40421668626368W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #16 south tank.

Note: labeling
inadequate.

Aug 28, 2024 9:56:32 AM
40.385435996577144N 107.4042328633368W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #17 center of
photo is pumpjack base.
Note: stored debris;
buckles, trash.

Aug 28, 2024 9:55:01 AM
40.38536307401955N 107.40392449311912W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #18 Pumpjack was pumping when staff arrived on location.

Aug 28, 2024 9:54:57 AM
40.38535733241588N 107.40392625331879W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:54:37 AM
40.385326612740755N 107.40382147952914W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #19 soil piled east
of wellhead. Note: oil
staining in pile.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #20 Pumping unit.

Aug 28, 2024 9:54:30 AM
40.38530854973942N 107.40378510206938W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:54:14 AM
40.385367893613875N 107.40386808291078W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #21 Pumping Unit.
Note: waxy oil staining at
wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:54:07 AM
40.385398445650935N 107.40388350561261W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #22 Pumping Unit.
Note: waxy oil staining at
wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:51:59 AM
40.38569248281419N 107.40425138734281W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #23 photo taken north of secondary containment. In middle of photo a game trail was observed. Staff walked down the trail.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:51:45 AM
40.38562614005059N 107.40427519194782W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #24 North side of
secondary containment.
Note: oil stained soil,
water, oil on water.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:51:19 AM
40.385682131163776N 107.40427175536752W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #25 Secondary
containment. Note: oil
stained soil, water, oil on
water.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:51:17 AM
40.38567882031202N 107.4042674805969W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #26 Photo taken looking south. Secondary containment. Note: oil stained soil, water, oil on water.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Aug 28, 2024 9:51:15 AM
40.38567358162254N 107.4042743537575W
Unnamed Road
Routt County
Colorado

Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #27 Secondary
containment. Note: oil
stained soil, water, oil on
water.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos

Location Name: Dill Gulch 1-17

Location ID: 107-06019

Inspection Date: 8/28/2024

Photo #28 Secondary containment. Note: oil stained soil, water, oil on water.

Aug 28, 2024 9:51:01 AM
40.385607783682644N 107.4042452685535W
Unnamed Road
Routt County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources