

Inspection Photos

ID: 480491

Operator: **CITATION OIL & GAS CORP**

Inspection Date: 8/28/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest toward the Arapahoe Unit Tank Battery. There is an oil leak out at the discharge pipe that must be controlled and cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480491 | Date: 8/28/2024

Inspection Photos



Photo 2. There is a puddle of oil at the discharge pipe that must be controlled, cleaned up, and contained.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480491 | Date: 8/28/2024

Inspection Photos



Photo 3. Facing northeast at the tank battery at the north side of the location. There is a pile of impacted material stored on location outside of secondary containment that must be removed and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID: 480491 | Date: 8/28/2024

Inspection Photos



Photo 4. The tank labeling is faded and/or missing.

