

Final Reclamation Inspection

August 21, 2024

Operator: S & D LLC - #10362

Location ID: 320737

Inspection Document #: 697505443

Arapahoe County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources



Photo 1. 2021 aerial imagery illustrates a portion of the access road between the red arrows where gravel has not been removed; therefore, decompaction has not been performed. Refer to Photo #2. In addition, the location has not been recontoured and decompaction has not been performed.

Inspection Photos
Location Name: KISSLER, DAN #1-10
Location ID: 320737



Photo 2. Photo taken from the southern location, facing South. Photo illustrates the approximate area where gravel has not been removed.



Photo 3. Photo taken from a portion of the location. Photo illustrates partially buried plastic which was observed throughout portions of the location.

Inspection Photos
Location Name: KISSLER, DAN #1-10
Location ID: 320737



Photo 4. Photo taken from the eastern location. Photo illustrates unused equipment/debris that remains.



Photo 5. Photo taken from the southern location. Photo illustrates unused equipment/debris that remains.



Inspection Photos
Location Name: KISSLER, DAN #1-10
Location ID: 320737



Photo 6. Photo taken from the southern location, facing West. Photo is trying to illustrate the location has not been recontoured but it is difficult to identify.